

Lieutenant Governor

## State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

## **Minerals Inspection Report**

Report Date:

07/07/2014

Reviewed

MY

Mine Name: UDOT Beck Street Mine Status: Permit Number: M/011/0003 Active Paid Operator Name: Lakeview Rock Products, Inc 05/01/2013 Permit Fees: Inspection Date: \$374,100 Inspector(s): L. Heppler Inspection Time: 4:00 PM **Bond Amount:** Attendee(s): John Burggraf Weather: Sunny, Dry Bond Escalation: 08/18/2011 Inspection Purpose: Routine annual inspection Prior Inspection: 04/24/2010

**Conclusions and Recommendations** 

At the time of inspection the site was used as a temporary storage site for construction. The mining had not commenced. It is also the recommendation of the Division that the operator interim seed areas that are disturbed, but not fully reclaimed. Interim seeding helps with dust suppression and reduces the chance for weeds to establish in disturbed areas. OGM to continue annual inspections and monitor the site when in the area.

	Elements of Inspection	Evaluated & Commented	Enforcemen
1.	Permits, Revisions, Transfer, Bonds		
	Permit feeis up to date. Bond due for escalation 08/18/2011.		
2.	Public Safety (shafts, adits, trash, signs, highwalls)		
	No deficiencies were noted		
3.	Protection of Drainages/Erosion Control		
	No external drainage noted, but weather was dry		
4.	Deleterious Material		
	Fuel was properly contained - see photo		
5.	Roads (maintenance, surfacing, dust control, safety)		
	Roads were minimal at the site.		
6.	Reclamation		
	No concurrent reclamation was noted		
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)		
	No regrading at the site		
8.	Soils		
	No soil stockpiles are noted		
9.	Revegetation		
	No revegetation was noted		
10.	Other		
	This line is intentionally left blank		

Inspector's Signature:

CC: Scott Hughes - Lakeview Rock Products

 $File: \ /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M011-Davis/M0110003-UDOTBeckStreetQuarry/inspections/INSP-03052013.pdf$ 



Mine: M/011/0003 Inspected: 05/01/2013



Overview of the site - looking east, from the bottom of the site



Overview of the site - looking east, from the bottom of the site



Overview of the site - looking east, from the bottom of the site



Overview of the site - looking east, from the bottom of the site

